



RADIANT HEATING AND COOLING SYSTEMS

proPANEL®

TECHNICAL BULLETIN



Incorrect Gasket



Correct Gasket

Affected Product

- proPANEL 90 (A3509000)
- proPANEL 90Z (A3509002)
- proPANEL 90M (A3509500)
- proPANEL 90MZ (A3509502)

How to Identify

Find the accessory pack in the panel. If the gaskets in the accessory pack are white, they are the incorrect gaskets.

Symptom

The white gaskets at the piping connections do not properly seal and will leak upon initial system test.

Resolution

For Contractors: If your proPANEL has the incorrect (white) gaskets, order the Universal Replacement Gasket Kit for proPANEL 90 Series (A3509290) through Uponor's RMA process at no cost to you. To replace the gasket, simply loosen the nut on the connection joint, remove the old gasket, install the new gasket and tighten the nut.

For Distributors: Check your inventory for affected gaskets. For proPANEL units with affected gaskets, return the proPANEL through Uponor's RMA process for replacement.

Contact your local Uponor representative or distributor for further information.



proPANEL 90 (A3509000)



proPANEL 90Z (A3509002)



proPANEL 90M (A3509500)



proPANEL 90MZ (A3509502)

Uponor, Inc.
5925 148th Street West
Apple Valley, MN 55124 USA
Tel: 800.321.4739
Fax: 952.891.2008
Web: www.uponor-usa.com

Uponor Ltd.
2000 Argenta Rd., Plaza 1, Ste. 200
Mississauga, ON L5N 1W1 CANADA
Tel: 888.994.7726
Fax: 800.638.9517
Web: www.uponor.ca