



Climate Cöntrol™ Multifunction Controller (A8020000)

# Uponor

RADIANT HEATING AND COOLING SYSTEMS

**CLIMATE CÖNTROL™  
MULTIFUNCTION  
CONTROLLER**

**TECHNICAL BULLETIN**

## Climate Cöntrol™ Multifunction Snow Melt Code Issue

### Affected Product

Climate Cöntrol™ Multifunction Controller (A8020000)

### Symptom

All devices associated with snow melt (boilers, primary pump, secondary or zone pumps, etc.) turn on when the outdoor temperature is within the Cold Weather Cutoff (CWCO) and Warm Weather Shutdown (WWSD).

### Issue

A coding error within the Multifunction Controller.

### Resolution

Uponor fixed the coding error.

### Corrective Action

For Multifunction Controllers issued prior to software release v1.5, return for warranty through Uponor's RMA (return materials authorization) process. Note that incomplete returns (missing parts, temporary cover, etc.) or products returned damaged from misuse will be refused.

Contact your local Uponor representative or distributor for further information.

**Uponor, Inc.**  
5925 148th Street West  
Apple Valley, MN 55124 USA  
Tel: 800.321.4739  
Fax: 952.891.2008  
Web: [www.uponor-usa.com](http://www.uponor-usa.com)

**Uponor Ltd.**  
2000 Argentia Rd., Plaza 1, Ste. 200  
Mississauga, ON L5N 1W1 CANADA  
Tel: 888.994.7726  
Fax: 800.638.9517  
Web: [www.uponor.ca](http://www.uponor.ca)