



RADIANT HEATING AND
COOLING SYSTEMS

**CLIMATE CÖNTROL™
MULTIFUNCTION
CONTROLLER
OUTDOOR SENSOR**

TECHNICAL BULLETIN



Climate Cöntrol™ Multifunction
Controller Outdoor Sensor (A9011001)

Climate Cöntrol™ Multifunction Controller Outdoor Sensor

Affected Product

Climate Cöntrol™ Multifunction
Controller Outdoor Sensor
(A9011001)

Reason for Issue

The 10k sensor used with the initial release of the Climate Cöntrol Multifunction Controller was not the original sensor approved for use with the controller. Because not all 10k sensors are the same, this led to a difference in temperatures over the mid scale.

Corrective Action

A new AIC (scale) was loaded into the Climate Cöntrol Multifunction Controller.

Contact your local Uponor representative or distributor for further information.

Uponor, Inc.
5925 148th Street West
Apple Valley, MN 55124 USA
Tel: 800.321.4739
Fax: 952.891.2008
Web: www.uponor-usa.com

Uponor Ltd.
2000 Argentia Rd., Plaza 1, Ste. 200
Mississauga, ON L5N 1W1 CANADA
Tel: 888.994.7726
Fax: 800.638.9517
Web: www.uponor.ca